

Dry Metal Bushes

| Product Code | Description | Physical Stock |
|---------------------|--------------------|-----------------------|
| 03DU06 | DRY METAL BUSH | 27 |
| 04DU04 | DRY METAL BUSH | 15 |
| 05DU08 | DRY METAL BUSH | 6 |
| 06DU08 | DRY METAL BUSH | 10 |
| 06DU12 | DRY METAL BUSH | 8 |
| 06DU22 | DRY METAL BUSH | 22 |
| 07DU08 | DRY METAL BUSH | 5 |
| 07DU12 | DRY METAL BUSH | 46 |
| 08DU06 | DRY METAL BUSH | 101 |
| 08DU08 | DRY METAL BUSH | 16 |
| 08DU10 | DRY METAL BUSH | 34 |
| 08DU12 | DRY METAL BUSH | 4 |
| 09DU08 | DRY METAL BUSH | 11 |
| 10DU08 | DRY METAL BUSH | 243 |
| 10DU10 | DRY METAL BUSH | 11 |
| 10DU12 | DRY METAL BUSH | 8 |
| 10DU14 | DRY METAL BUSH | 18 |
| 11DU14 | DRY METAL BUSH | 33 |
| 12DU08 | DRY METAL BUSH | 14 |
| 12DU12 | DRY METAL BUSH | 16 |
| 12DU16 | DRY METAL BUSH | 43 |
| 12DX08 | DRY METAL BUSH | 8 |
| 14DU12 | DRY METAL BUSH | 9 |
| 14DU16 | DRY METAL BUSH | 12 |
| 14DX16 | DRY METAL BUSH | 12 |
| 16DU12 | DRY METAL BUSH | 5 |
| 16DU20 | DRY METAL BUSH | 11 |
| 16DU24 | DRY METAL BUSH | 105 |
| 16DX12 | DRY METAL BUSH | 6 |
| 16DX16 | DRY METAL BUSH | 14 |
| 18DU12 | DRY METAL BUSH | 8 |
| 18DU16 | DRY METAL BUSH | 10 |
| 20DU20 | DRY METAL BUSH | 47 |
| 20DU28 | DRY METAL BUSH | 4 |
| 20DX20 | DRY METAL BUSH | 14 |
| 22DU16 | DRY METAL BUSH | 6 |
| 22DU22 | DRY METAL BUSH | 7 |
| 242624 | DRY METAL BUSH | 109 |
| 24DU20 | DRY METAL BUSH | 49 |
| 24DU24 | DRY METAL BUSH | 9 |
| 24DX16 | DRY METAL BUSH | 8 |
| 24DX20 | DRY METAL BUSH | 4 |
| 24DX24 | DRY METAL BUSH | 10 |
| 26DU24 | DRY METAL BUSH | 11 |
| 26DX24 | DRY METAL BUSH | 12 |
| 28DU24 | DRY METAL BUSH | 8 |
| 28DU32 | DRY METAL BUSH | 6 |
| 28DX28 | DRY METAL BUSH | 4 |
| 32DU24 | DRY METAL BUSH | 7 |
| 32DU32 | DRY METAL BUSH | 6 |
| 32DX32 | DRY METAL BUSH | 6 |
| 36DX32 | DRY METAL BUSH | 1 |
| 36DX36 | DRY METAL BUSH | 11 |
| 44DU32 | DRY METAL BUSH | 3 |
| 48DX32 | DRY METAL BUSH | 4 |
| 64DX48 | DRY METAL BUSH | 1 |

| | | |
|----------------|------------------------|-----|
| A350FM-2528-21 | IGUS BUSH | 16 |
| DU06 | DRY METAL WASHER | 1 |
| DU08 | DRY METAL WASHER | 1 |
| FMB0604DU | DRY METAL BUSH FLANGED | 50 |
| FMB089.5DU | DRY METAL BUSH FLANGED | 20 |
| FMB1007DU | DRY METAL BUSH FLANGED | 10 |
| FMB1207DU | DRY METAL BUSH FLANGED | 10 |
| FMB1209DU | DRY METAL BUSH FLANGED | 6 |
| FMB1217DU | DRY METAL BUSH FLANGED | 17 |
| FMB1412DU | DRY METAL BUSH FLANGED | 10 |
| FMB1612DU | DRY METAL BUSH FLANGED | 50 |
| FMB1617DU | DRY METAL BUSH FLANGED | 2 |
| FMB2022DU | DRY METAL BUSH FLANGED | 97 |
| FMB3526DU | DRY METAL BUSH FLANGED | 10 |
| FMB4026DU | DRY METAL BUSH FLANGED | 13 |
| JEM-40-21 | IGUS BUSH | 2 |
| MB0404DU | DRY METAL BUSH | 39 |
| MB0406DU | DRY METAL BUSH | 30 |
| MB0505DU | DRY METAL BUSH | 189 |
| MB0606DU | DRY METAL BUSH | 190 |
| MB0608DU | DRY METAL BUSH | 80 |
| MB0610DU | DRY METAL BUSH | 20 |
| MB0710DU | DRY METAL BUSH | 71 |
| MB0808DU | DRY METAL BUSH | 24 |
| MB0810DU | DRY METAL BUSH | 13 |
| MB0812DU | DRY METAL BUSH | 50 |
| MB10070DU | DRY METAL BUSH | 8 |
| MB1008DU | DRY METAL BUSH | 123 |
| MB1010DU | DRY METAL BUSH | 35 |
| MB1012DU | DRY METAL BUSH | 237 |
| MB1015DU | DRY METAL BUSH | 17 |
| MB1212DU | DRY METAL BUSH | 10 |
| MB1215DU | DRY METAL BUSH | 6 |
| MB1220DU | DRY METAL BUSH | 12 |
| MB125100DU | DRY METAL BUSH | 2 |
| MB1320DU | DRY METAL BUSH | 2 |
| MB1415DU | DRY METAL BUSH | 14 |
| MB1420DU | DRY METAL BUSH | 8 |
| MB1515DU | DRY METAL BUSH | 26 |
| MB1525DU | DRY METAL BUSH | 6 |
| MB1615DU | DRY METAL BUSH | 8 |
| MB1620DU | DRY METAL BUSH | 15 |
| MB1625DU | DRY METAL BUSH | 47 |
| MB1715DU | DRY METAL BUSH | 12 |
| MB1720DU | DRY METAL BUSH | 18 |
| MB1815DU | DRY METAL BUSH | 20 |
| MB1825DU | DRY METAL BUSH | 63 |
| MB1825DUM | DRY METAL BUSH | 2 |
| MB2015DU | DRY METAL BUSH | 24 |
| MB2020DU | DRY METAL BUSH | 21 |
| MB2025DU | DRY METAL BUSH | 13 |
| MB2030DU | DRY METAL BUSH | 40 |
| MB2215DU | DRY METAL BUSH | 11 |
| MB2415DU | DRY METAL BUSH | 10 |
| MB2515DU | DRY METAL BUSH | 51 |
| MB2520DU | DRY METAL BUSH | 23 |
| MB2525DU | DRY METAL BUSH | 15 |
| MB2530DU | DRY METAL BUSH | 6 |

| | | |
|---------------|----------------|-----|
| MB2550DU | DRY METAL BUSH | 12 |
| MB2820DU | DRY METAL BUSH | 4 |
| MB2830DU | DRY METAL BUSH | 8 |
| MB3015DU | DRY METAL BUSH | 38 |
| MB3020DU | DRY METAL BUSH | 19 |
| MB3025DU | DRY METAL BUSH | 4 |
| MB3030DU | DRY METAL BUSH | 29 |
| MB3040DU | DRY METAL BUSH | 34 |
| MB3230DU | DRY METAL BUSH | 10 |
| MB3240DU | DRY METAL BUSH | 12 |
| MB3255DU | DRY METAL BUSH | 14 |
| MB3520DU | DRY METAL BUSH | 15 |
| MB3530DU | DRY METAL BUSH | 4 |
| MB3535DU | DRY METAL BUSH | 17 |
| MB3550DU | DRY METAL BUSH | 13 |
| MB4020DU | DRY METAL BUSH | 10 |
| MB4030DU | DRY METAL BUSH | 8 |
| MB4040DU | DRY METAL BUSH | 11 |
| MB4050DU | DRY METAL BUSH | 4 |
| MB4530DU | DRY METAL BUSH | 5 |
| MB4540DU | DRY METAL BUSH | 8 |
| MB4545DU | DRY METAL BUSH | 4 |
| MB4550DU | DRY METAL BUSH | 18 |
| MB5040DU | DRY METAL BUSH | 25 |
| MB5050DU | DRY METAL BUSH | 4 |
| MB5060DU | DRY METAL BUSH | 4 |
| MB5540DU | DRY METAL BUSH | 7 |
| MB5550DU | DRY METAL BUSH | 10 |
| MB5560DU | DRY METAL BUSH | 14 |
| MB6040DU | DRY METAL BUSH | 6 |
| MB6060DU | DRY METAL BUSH | 7 |
| MB6070DU | DRY METAL BUSH | 4 |
| MB6570DU | DRY METAL BUSH | 4 |
| MB7040DU | DRY METAL BUSH | 10 |
| MB7070DU | DRY METAL BUSH | 2 |
| MB7540DU | DRY METAL BUSH | 9 |
| MB7550DU | DRY METAL BUSH | 10 |
| MB7580DU | DRY METAL BUSH | 4 |
| MB8060DU | DRY METAL BUSH | 6 |
| MB8070DU | DRY METAL BUSH | 4 |
| MB8080DU | DRY METAL BUSH | 8 |
| MB9060DU | DRY METAL BUSH | 7 |
| MB95100DU | DRY METAL BUSH | 3 |
| MB9560DU | DRY METAL BUSH | 6 |
| PCMF252811.5E | DRY METAL BUSH | 8 |
| PM10080DX | DRY METAL BUSH | 2 |
| PM125100DX | DRY METAL BUSH | 4 |
| PM1720DX | DRY METAL BUSH | 10 |
| PM2015DX | DRY METAL BUSH | 7 |
| PM2020DX | DRY METAL BUSH | 165 |
| PM2220DX | DRY METAL BUSH | 4 |
| PM2225DX | DRY METAL BUSH | 127 |
| PM2415DX | DRY METAL BUSH | 10 |
| PM2520DX | DRY METAL BUSH | 13 |
| PM2525DX | DRY METAL BUSH | 20 |
| PM2530DX | DRY METAL BUSH | 10 |
| PM2830DX | DRY METAL BUSH | 10 |
| PM3020DX | DRY METAL BUSH | 31 |

| | | |
|-----------|------------------|-----|
| PM3030DX | DRY METAL BUSH | 12 |
| PM3040DX | DRY METAL BUSH | 15 |
| PM3520DX | DRY METAL BUSH | 30 |
| PM3530DX | DRY METAL BUSH | 10 |
| PM3540DX | DRY METAL BUSH | 9 |
| PM3550DX | DRY METAL BUSH | 28 |
| PM4020DX | DRY METAL BUSH | 12 |
| PM4025DX | DRY METAL BUSH | 1 |
| PM4030DX | DRY METAL BUSH | 17 |
| PM4040DX | DRY METAL BUSH | 10 |
| PM4050DX | DRY METAL BUSH | 6 |
| PM4530DX | DRY METAL BUSH | 1 |
| PM4540DX | DRY METAL BUSH | 10 |
| PM5040DX | DRY METAL BUSH | 7 |
| PM5060DX | DRY METAL BUSH | 14 |
| PM5520DX | DRY METAL BUSH | 2 |
| PM5560DX | DRY METAL BUSH | 4 |
| PM6040DX | DRY METAL BUSH | 60 |
| PM6060DX | DRY METAL BUSH | 15 |
| PM6070DX | DRY METAL BUSH | 4 |
| PM7040DX | DRY METAL BUSH | 6 |
| PM7050DX | DRY METAL BUSH | 4 |
| PM7070DX | DRY METAL BUSH | 2 |
| PM7550DX | DRY METAL BUSH | 2 |
| PM80100DX | DRY METAL BUSH | 3 |
| WC10DU | DRY METAL WASHER | 8 |
| WC12DU | DRY METAL WASHER | 14 |
| WC14DU | DRY METAL WASHER | 6 |
| WC16DU | DRY METAL WASHER | 18 |
| WC18DU | DRY METAL WASHER | 3 |
| WC20DU | DRY METAL WASHER | 6 |
| WC24DU | DRY METAL WASHER | 15 |
| WC24DX | DRY METAL WASHER | 191 |
| WC25DU | DRY METAL WASHER | 19 |
| WC25DX | DRY METAL WASHER | 4 |
| WC30DU | DRY METAL WASHER | 10 |
| WC30DX | DRY METAL WASHER | 18 |
| WC35DX | DRY METAL WASHER | 4 |
| WC40DU | DRY METAL WASHER | 18 |
| WC40DX | DRY METAL WASHER | 37 |
| WC50DU | DRY METAL WASHER | 10 |
| WC50DX | DRY METAL WASHER | 8 |
| WC60DX | DRY METAL WASHER | 6 |

Updated 11th October 2022